

## PAD REPLACEMENT FRONT X-MAX 250 MY 2005-2009

Here is a brief guide with pictures for replacing the tablet front, I hope it is useful: Unscrew the bolts A and B that hold the caliper to the fork lockout.

With C I have indicated the sliding pin of the tablets that once removed the clip on the outside must be unscrewed from the inner side (wheel).



**Unscrew the pin D.**



**At this point, remove the tablet from the right, then push the left one on the stop to retract the pistons, and then pull**





Finally also disassemble the two plates X and Y in steel, clean and grease them, as the sliding pin K.

Do this with the lithium grease.



Finally also disassemble the two plates X and Y in steel, clean and grease them, as the sliding pin K.

Do this with the lithium grease.

Once this is done you can put it back together in this sequence: (1) Platelet X and Y, (2) tablets, (3) slide rod K (D tighten to 7 N / m) (4) Secure the pin with Seeger C ( 5) A and B bolts (tighten to 40 N / m)

Then press the brake lever several times to reposition the pads against the disc